



Channels

Gas temperature

Question:

Exhaust gas thermocouple (EGT) shows unexpected values.

Answer:

Check that the sensor is correctly installed. If the problem persists replace the sensor. Newer sensors are more resistant and can be identified by their curve shape.