





Introduction

The magneto-resistive speed sensor is a high-sensing distance instrument which will allow you to measure the rotational speed. This sensor is a "non contact" device and needs a magnetic metal trigger to pass the sensor face.

The sensor sensing distance is from 8 mm to 20 mm; the speed sensor is supplied with a 1700 mm long cable.

Kit description

Inside the magneto-resistive speed sensor kit you find the following objects:

- 1 metal plate, equipped with a magnetic cylinder;
- 1 speed sensor.

Installation notes

- Install the magnetic metal plate;
- Install the speed sensor on a self-made bracket; use the locknuts provided to fasten the sensor;
- When mounting the sensor, please let the sensible part pass in front of the magnetic cylinder at a distance between 8 and 20 mm;
- Plug the speed sensor in your data logger (MyChron 3, EVO 3, Dash ST1...);
- Do not place the sensor near magnetic sources of electrical interference.



Software

Once the speed sensor has been installed and plugged in your data logger, to acquire consistent and correct information, it is necessary to configure it. To do so, please use **Race Studio 2**, the software properly developed by Aim to configure its instruments and analyze stored data.

Race Studio 2

In **Race Studio 2** main window you can choose your instrument. Once selected it, please press "*System manager*" button.

Sensor configuration – EVO 3, Dash ST1

In *"System manager"* main window, press *"Channels"* button to set the sensor you have installed on your vehicle. The following screenshot appears.

Gened	F. Date 1		Denait	and a second		Contrain Prove 1			
1.01171	Logipe siles	finder	Trend			2.04	0000	C#	ene :
[Channel she	(name in	Dane	Longingto	Second land	annal 1	come banara.	Joint brings	Parmi 1	Farm 2 -
DOM:	Eveloped	Engele	18 Mg	(right level) (great	ales .	0.000	21000-000		27000
1.1PD_1	Englind	Speed_5	10 Hz	liped	Ana/h-	0.000	(76) 000	1100.000	1000
110.1	Double	Speed 2	1244	Ipaint	Add -	2,005	250 000	1000.000	
1011	England	Charmel, 1	1544	A Barrussiak		-5.000	156.000		
DU	Enabled	Owned, J	18 14	a summaries of a	1 1	100	10.000		
K CH_R	England	Owned,3	12 44	Parage V00 65 ha	211	1.00	1100 000		
DI.4	English	Charved 4	1044	Pressure VOID 1-10 tax	12	1.000	5082-000		
DIS	English	Channel 5	10.44	Lowing netted acceleration	12	0.008	190,000		
101.6	E-still	Channel S	12144	Futerholene delance	12	1.000	10.00 0000		
DUT	Ended	Owned, 7	15 Mg	Md Sex Interfactories	12	0.010	1181.000		
1.091.9	Empland	David 8	10.46	Lankda-cond	12	0.000	100.000		
ATT 8	England	Are 1	10 Hz	Lankole used Mills, TL7111	-	-1000	5 1000		
ALC: I	England	Alc.T	10444	Longholts of Acceleration		3.000	8 000		
109 Tem	Evaluat	Datalogan, Tang	1010	Calculat	1	100	100.000		
194	A.4.1	Trine and				-			

To configure the speed sensor, please click twice in the "Param 1" column and in the row corresponding to "speed" channel and select "speed". The following screenshot appears:

Chann	el Name	Sensor lys	Measure uni	
Spe	red_1	Speed		km/h
1	Wheel circumference: Pulses per wheel revolution:		1666	(mm)

You are requested to set two parameters:

- *Number of pulses on wheel revolution*: this function allows you to set the number of pulses per wheel revolution. Please fill this box with the number of teeth on the gear wheel.
- *Wheel circumference*: this option you to set the wheel circumference (in mm or in inches). This value is fundamental to correlate the wheel revolution speed and the bike speed.

Once the correct wheel circumference value and the number of pulses have been set, transmit the configuration to the instrument pressing *"Transmit"* button.

Sensor configuration – MyChron 3 BIKE

In "System manager" main window, press "Configuration" button to set the speed sensor parameters. The following screenshot appears.



To acquire a correct speed signal, you are requested to set two parameters:

- *Number of pulses on wheel revolution*: this function allows you to set the number of pulses per wheel revolution. Please fill this box with the number of teeth on the gear wheel.
- *Wheel circumference*: this option allows you to set the wheel circumference (in mm or in inches). This value is fundamental to correlate the wheel revolution speed and the bike speed.

When the correct wheel circumference value and the number of pulses have been set, it is necessary to transmit the configuration to the instrument pressing "*Transmit*" button.



Dimensions



Connector details

Pin	Function	Pin	Function	
1 2	Speed GND	3 4	V battery n.c.	



4 pins Binder 719 male connector: solder termination view

Technical characteristics

Electrical characteristics	Value
Supply voltage	6-24 V DC
Supply current	13.5 mA
Output signal type	Pulse 0-5 Volts
Maximum output current	20 mA
Maximum operating frequency	100 kHz
Maximum sensing distance	20 mm
Recommended distance	10 mm
Number of pulses per revolution	1
Mechanical characteristics	Value
Operating temperature range	From -20 to +85 °C
Cable length	1700 mm