



Interferences

## RPM Cable

---

**Question:**

The manual says to coil RPM cable many times, why AiM does not give this suggestion?

**Answer:**

In 2T engines the signal is strong enough: coiling many times the RPM cable on the sparkplug wire could generate electromagnetic interferences, causing issues like these described in the first paragraph.